


**Cause :**

If user didn't add NVR IP address in the trust website list, they might encounter this kind of situation.

**Solution:**

Please follow below steps to add NVR IP address in Safari trust side.


**Step1:** Please go to the safari Preferences setting.



**Step2:** And then go the Security --->Manage Website Settings



**Step3:** And by default it will be "allow", Please choose "run in unsafe mode"



**Step4:** Please add your server IP as trust site.



**Step5:** Finish the setting and refresh again.